


Corrosion Evaluation and Mitigation of Bonded Post-Tensioning

Presented by:

Ben Armitage & Pratik Murkute

VCS Engineering, Inc.



Outline

- Post-tensioning Background
- Common problems found in post-tensioning
- How to detect the problems – Testing methods
- How to rehabilitate and mitigate the problems

History

- Eugene Freyssinet proposed the use of Post-tensioned concrete in 1928
- First PT bridge built in France in 1941
- Post-tensioning gains popularity in Europe due to steel shortage: 1946
- First PT bridge in US: 1949 - 1951
- Structurally efficient, long span bridges

JFK Memorial Causeway, Corpus Christi, Texas


First Precast Segmental Bridge built in USA (1973)



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

What are the common problems?

Defective Grout (Segregation)




Grout Voids -Unprotected Strands



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Corrosion






Bleed Test

Wick-induced bleed test by
American Segmental Bridge
Institute (April 2012)

Portland cement
grout ~ 4% bleeding after
24 hours of
grout operation.




Straight vs Deviated Tendon



How do we find these problems?

Ground Penetrating Radar




Locating Ducts

Mark the tendon path every 1 ft.



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Impact Echo





Duct with a Soft Grout or Void Defect

Resonant frequency lowered due to increased wave path


Fully Grouted Duct

Resonant frequency related to slab thickness

Impact Echo




Pulse Velocity




Testing Speed



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency



No Defect in PT Tendon



Possible Grouting Defect

Borescope Inspection



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Typical Defects



Void Bottom Corrosion on
Duct & Tendons



Corrosion on Duct &
Tendon



Void in Pier With Dywidag
Bar Instead of Tendons



Corrosion on Duct




Void With Tendon
Corrosion



Anchor Plate, Tendons &
Duct are Grout Coated




Anchor Close-Up, Top of
Tendons Show Corrosion




Tendon Found with
Standing Water Inside


Moisture Testing



Post-Tech CE Corrosion Evaluation Grading Chart



Corrosion Rate



Moisture (RH)



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Case History of 3 Bridge PT Evaluation

Bridges Inspected

- Pedestrian Bridge
 - Cracking along exterior of PT girders
 - Leaking efflorescence
 - Pedestrian bridge with 2 PT spans crossing a state highway
 - Single box spans with 2 tendons per span
- Twin Eastbound/ Westbound bridges
 - WB- 4 span bridge carrying the highway as an overpass
 - EB - 3 span bridge carrying the highway as an overpass
 - Three cell box girders with 3 tendons in each web (12 tendons/span)

Inspection Technique

- Testing 100% of the PT - \$\$\$
- VCS performed targeted testing focused 15 feet along PT tendons
 - 15 feet from **anchor locations**
 - 15 feet in both directions from **high points** at piers
- Impact echo/pulse velocity (IE/PV) located potential defects
 - Confirmed by drilling and borescope inspection
 - Suspect locations were drilled and documented (borescope)





Pedestrian Bridge


- IE/PV identified the presence of lens voids and soft grout in one tendon



Pedestrian Bridge

- Defects identified in west girder

LEGEND	
	VOID
	NO VOID
	LENS VOID
	SOFT GROUT




WB Bridge

- Previous inspections employed drilling in random locations to identify voided tendon ducts.
 - Some remedial grouting repairs
- VCS identified a large void that was approximately **48 feet** long



WB Bridge


- Largest identified void of 48 feet




NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

EB Bridge

- Previous inspections by random drilling
 - No remedial grouting in the past
- Largest void identified over **20 feet** long



EB Bridge



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Investigation Summary


- Few defects identified in Pedestrian Bridge
- Large voids found in WB and EB Bridges
- Strands are generally in good condition
 - Corrosion ranging from mild to moderate
 - No broken strands or wires identified

Rehabilitation and Mitigation Strategies of PT


Rehabilitation

- Challenges
 - How can we stop or prevent deterioration of tendons?
 - Especially when we know grout defects exist
 - Access along length extremely difficult
 - Particularly with Embedded ducts
- Rehab Options
 - Drying
 - If there is moisture along the tendon
 - PT Impregnation material
 - Coats steel to prevent corrosion
 - Displaces water
 - Permeates into voids and concrete
 - Regrouting
 - Severely Voided

PT Drying



PT Drying




NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Monitoring of Drying Process




NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

PT Drying- Performance




PTCE Before Drying Process




PTCE After Drying Process

Post Tension Impregnation (PTI) Process


- Corrosion protection process for grouted PT tendons with voids or defective grout
- Impregnation material transported inside strands full length of tendon
- Impregnation material reduces corrosion by:
 - Coating exposed steel in voids
 - Improving corrosion resistance of grout



Access



End Port



Intermediate Access Port



Anchor Cap Removal



Original Anchor Cap



Grout



Exposed Strands
after Grout Removal

IMPREGNATION



Impregnation at Tendon End



Impregnation Material Appear at Far End

VERIFICATION



Impregnation nearing completion



Inspection opening and removal of grout to verify presence of impregnation material



Impregnation material visible along all PT strands



Performance Validation

Interim Report:

Evaluation of a Silicon Based Polymer Corrosion Inhibitor for Post-Tensioned Tendons

K. Bergum
T. Risher
State Materials Office
Corrosion/Durability Laboratory
March 1, 2017

State Materials Office – Corrosion Research Laboratory, 5007 N.E. 39th Avenue, Gainesville, FL 32608, ph (352) 355-6600

Page | 1



NATIONAL BRIDGE PRESERVATION CONFERENCE 2024
Innovation for Infrastructure Resiliency

Summary

- PT tendons are susceptible to corrosion
- Evaluation techniques are available to determine the cause, extent and location of problems
- Corrosion mitigation techniques are available to protect and extend the service life of PT tendons in existing structures

Thank you

Questions?

Ben Armitage

Research & Development Manager
VCS ENGINEERING | NDT Division
Mobile: 813-469-0216
BArmitage@VCS-NDTDivision.com

Pratik Murkute

Ph.D., NACE CP Technologist
Senior Project Engineer | VCS ENGINEERING
Mobile: 813-310-1245
Pratikm@vcs-engineering.com